

Porsche 911

VIN: **WP0ZZZ99Z5S731044**

Petrol

2004

Generated on **2023-08-10 12:02**



Theft



Odometer



**Financial and legal
status**



Damage



Things to know about Porsche 911 2004

 AI generated

The Porsche 911 of 2004 came in several different engine options, including a 3.6-liter flat-six engine that delivered 320 horsepower and 273 lb-ft of torque, a 3.8-liter flat-six engine that produced 355 horsepower and 295 lb-ft of torque, and the high-performance Turbo model that boasted a 3.6-liter flat-six engine with twin-turbochargers that achieved an impressive 415 horsepower.

Additionally, the Porsche 911 of 2004 was offered in a variety of body styles, including the standard Coupe, Cabriolet, and the sleek Targa. The Coupe and Cabriolet models offered a sporty and nimble driving experience, while the Targa incorporated a retractable roof that allowed for an open-air driving experience without compromising the car's rigidity.

It's noteworthy to mention that regardless of the body style or engine option chosen, the Porsche 911 of 2004 came standard with rear-wheel drive, which provided exceptional handling and a dynamic driving experience.

Other standout features included a 6-speed manual transmission or an optional 5-speed automatic with steering-wheel-mounted paddle shifters, a state-of-the-art Bose sound system, and an array of advanced safety technologies, such as traction control

and stability control, to ensure the vehicle remained stable and secure under any driving conditions.

Overall, the Porsche 911 of 2004 offered exceptional performance, unparalleled driving dynamics, and extraordinary refinement no matter which engine or body style was chosen. This is a true sports car icon that still impresses and holds its value to this day.

This description is AI-generated and has not undergone human review for potential inaccuracies.

Theft

Is the vehicle currently marked as stolen? Was it stolen in the past? Has it been recovered?



We didn't find any records that the vehicle was stolen.

Here's what we checked:



Currently wanted as stolen

✓ No record found



Stolen in the past

✓ No record found

Current status unknown



Stolen in the past

✓ No record found

Vehicle has been recovered

Police database stolen vehicle **check completed in:**



United Kingdom



Slovakia



Sweden



Canada



Romania



Czechia

Odometer


Are there signs of mileage roll backs or discrepancies?



Last known mileage: 73,150 mi



19 mileage records found



Odometer records

2004-01	6 mi
2007-02	9,568 mi
2007-09	15,891 mi
2008-05	17,945 mi
2009-05	23,682 mi
2010-05	29,048 mi
2011-05	34,323 mi
2011-05	34,371 mi
2012-04	37,493 mi
2013-07	43,310 mi

Odometer records

2014-06	61,024 mi
2015-06	62,589 mi
2016-06	64,403 mi
2017-06	65,223 mi
2018-06	66,213 mi
2019-06	69,915 mi
2020-06	70,857 mi
2021-06	72,403 mi
2022-06	73,150 mi

Financial and legal status

Has the vehicle passed its technical inspections? Does it have property rights restrictions or outstanding loans?



Tech inspection is valid

Legal



MOT (technical inspection)

Passed 2022-06

United Kingdom

Has successfully passed technical inspection

Valid until 2023-07

- Offside Rear Tyre worn close to legal limit/worn on edge on 1.6mm (5.2.3 (e))
- Engine covers and undertrays fitted unable to check certain items
- Offside Front Coil spring corroded slight corrosion (5.3.1 (b) (i))
- Nearside Rear Tyre worn close to legal limit/worn on edge on 1.6mm (5.2.3 (e))
- Offside Front Shock absorbers has slight external damage to the casing corrosion (5.3.2 (b))
- Nearside Front Coil spring corroded slight corrosion (5.3.1 (b) (i))
- Nearside Front Shock absorbers has slight external damage to the casing corrosion (5.3.2 (b))



Scrap

✓ No record found

No record that vehicle was marked as scrapped



Exported

✓ No record found

No export records found



Imported

✓ No record found

No import records found

Outstanding finance



Lease

✓ No record found

No data available on outstanding loan or finance agreement



Operating-lease

✓ No record found

No record of vehicle being on an operating-lease



Unit-stocking

✓ No record found

No record of vehicle being under unit-stocking finance

Damage

Has this vehicle been damaged in the past? What was the value of the damages?



No damage records found

Damage records



✓ No damage found

Occasional inaccuracies can occur, especially when checking older vehicles. Illegitimate mechanical garages may illegally disguise vehicle defects or damages, not recording their existence anywhere. Sometimes, even vehicle VIN plates may be

replaced. We have a variety of methods to detect even such crimes, but it's impossible to provide a 100% guarantee.

Emissions

How much CO₂ emissions do vehicles of this model/year produce?



Vehicle CO₂ emissions: 277 g/km

CO₂ emissions

Up to 100

101 - 120

121 - 140

141 - 165

166 - 185

Your vehicle CO₂ emission

277 g/km Tax band **M**

Emission CO₂ g/km

Specs

What specs and equipment are on record for this vehicle?



Check whether the specs and equipment of this vehicle match the facts given by the seller.

Identification and technical specifications



Make
Porsche



Model
911



Variant
**911 Carrera S
Cabriolet**



Manufacture year
2004



Fuel type
Petrol



Gearbox type
Manual

Timeline

24 records found

The timeline of records for this vehicle

Latest records

2004-01

 **Country unknown**



Was manufactured

The country indicates either the location of manufacturing facility, assembly plant or registration address of the manufacturer. The date may be approximate.

2007-02

 **United Kingdom**



Was registered

The record represents an administrative event. This could be related to a change of ownership, documents, etc

2007-02

 **United Kingdom**



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2007-09

 **United Kingdom**



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2008-05

 **United Kingdom**



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2009-05

 **United Kingdom**



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2010-05

 **United Kingdom**



Failed a technical inspection

A failed technical inspection (MOT) was recorded in the indicated country. Unsuccessful emission tests will also fall under the same category.

- Nearside Headlamp aim too low (1.8)
- Offside Registration plate lamp not working (1.1.5c)
- Offside Front brake disc slightly scored (3.5.1h)
- Offside Rear brake disc slightly scored (3.5.1h)
- Offside Headlamp aim too low (1.8)
- Nearside Front brake disc slightly scored (3.5.1h)
- Nearside Rear brake disc slightly scored (3.5.1h)

2010-05

 **United Kingdom**



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2011-05

 **United Kingdom**



Failed a technical inspection

A failed technical inspection (MOT) was recorded in the indicated country. Unsuccessful emission tests will also fall under the same category.

- Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)
- Nearside rear brake juddering slightly (3.7.A.5b)
- Offside front brake juddering slightly (3.7.A.2b)
- Nearside rear brake binding (3.7.B.1)
- rear brake disc rusty
- Offside Rear An item not tested (Manual)
- Offside Rear Tyre has ply or cords exposed (4.1.D.1b)
- Offside rear brake juddering slightly (3.7.A.5b)
- Offside rear brake binding (3.7.B.1)
- rear brake disc rusty
- Nearside Rear An item not tested (Manual)

2011-05

 **United Kingdom**



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2012-04



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2013-07



Failed a technical inspection

A failed technical inspection (MOT) was recorded in the indicated country. Unsuccessful emission tests will also fall under the same category.

- Supplementary Restraint System warning lamp indicates a fault (5.4.2)

2013-07



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2014-05



Had licence plate changed

This vehicle's licence plate has changed.

From: **777CJX** To: **AY54JVH**

2014-06



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2014-06



Ownership changed

The country indicated the geographical location of a documented ownership change or renewal. Please note that some changes may be formal, e.g., end-of-lease transfers and similar.

2015-06



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2016-06



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2017-06



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2018-06



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2019-06



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2020-06



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2021-06



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2022-06



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.